








- PRELIMINARY DRAWING -
Update will follow









10 (NEW)



11 (NEW)









PJ 600

81




82



SJ 600

87


88




CH 600

83


84




89



90




91



CW 600

85

86



Position	Code	description
1	BR67051134	PROTECTION
2	BR67002500	SPRING
3	BR67002496	SPRING
4	BR67000501	LEVER
005A	BR63205640	Upper p.c.b.
005B	7322010284	PCB (220/240V 50/60Hz)
005C	7322010884	MOTOR PCB (INT)
7	BR67000504	JOINT
9	7322010254	BODY
10	7322010304	SWITCH
11	7322010274	PUSH BUTTON
12	BR67000495	Button
13	BR67051067	SPRING
14	BR67002499	SPRING
15	BR67000505	GASKET
16	BR67000977	SPRING
17	BR67002755	CARBON BRUSH
18	7322010874	POWER HANDLE (INT) (220-240V 50-60Hz 600W 14.000 RPM)
19	BR67002502	FERRITE TUBE
020A	BR67001975	BLACK CABLE
021B	7322010914	CABLE GUIDE FOR MOTOR
22	BR67000297	WASHER (82X12X05)
23	BR67000503	RUBBER PAD
24	BR63205625	Supporting frame
25	BR67051152	SCREW TORX (4X1)
28	BR63202626	PULLEY
029A	BR67002501	BELT
029B	7322010894	TOOTHED BELT
32	7322010954	ICS FP3XXX POWERCORD FOR ABJ MOTOR CN
34	BR67000502	FOOT
37	BR67000506	SWITCH CAM
38	BR67002426	INSULATOR
60	BR67051073	TAMPER
61	AS00005625	CONTAINER LID
62	AS00005626	PURE' KNIFE
64	BR67051141	KNEADING HOOK

66	BR67051142	PROTECTION
67	BR67051143	WHIPPING ATTACHMENT COMBIMAX
68	AS00005622	CONTAINER
70	BR67000488	GRATING INSERT
71	BR67000490	COARSE SLICING INSERT
72	BR67000489	FINE SLICING INSERT
73	BR67000492	COARSE SHREDDING INSERT
74	BR67000491	FINE SHREDDING INSERT
76	AS00005628	INSERT CARRIER
300	BR63205630	LABEL
1001	BR67051113	TORX SCREW
1002	BR64000159	SUPPORT
1003	BR67051114	TORX T-15H HEXAGONAL INSERT (50 MM)
1004	BR64889120	COVER DISASSEMBLY TOOL
1005	BR64889121	Torx T-10 hexagonal insert 70 mm